



Charts


Test ID: 16808736 Average: 4.9 pCi/L




Average Temperature 69°F



Average Relative Humidity 47.6%



Average Barometric Pressure 28.4"Hg



All internal cross checks passed.

Job ID: 12
 Serial Number: 5106058
 Cal. Factor [BKG]: 0.3846 cpm [0.15 cpm]
 Test Period: 07-06-2013 @ 14:57 07-08-2013 @ 16:57
 Counts [Time]: 6100 [50 hours]
 Avg Radon Level: 4.9 pCi/l ± 0.2

Client: P6385 Tests Remaining: 12
 ITHACA-RADON
 TRACIE EVANS
 124 SEVEN MILE DR
 ITHACA, NY 14850
 Phone: 607-351-4610 Fax:
 Email: TRACIELYNNEVANS@GMAIL.COM

Hour	pCi/l	%RH	BP	Temp.	Hour	pCi/l	%RH	BP	Temp.
1	2.4	44%	29.1	77	49	3.6	47%	28.6	70
2	2.2	46%	28.8	71	50	3.8	48%	28.5	69
3	2.9	46%	28.6	70					
4	4.0	47%	28.6	70					
5	3.0	47%	28.5	69					
6	3.8	47%	28.5	69					
7	2.1	47%	28.5	69					
8	3.5	47%	28.5	69					
9	3.2	47%	28.5	69					
10	3.9	47%	28.5	69					
11	3.8	48%	28.5	69					
12	5.2	48%	28.5	69					
13	5.0	48%	28.5	69					
14	5.6	48%	28.5	69					
15	6.8	48%	28.5	69					
16	6.8	48%	28.5	69					
17	6.5	48%	28.5	69					
18	6.8	48%	28.5	68					
19	6.9	48%	28.3	68					
20	6.1	48%	28.3	68					
21	5.9	48%	28.5	68					
22	5.3	48%	28.3	68					
23	6.1	48%	28.3	68					
24	5.6	48%	28.3	68					
25	5.3	48%	28.3	68					
26	4.6	48%	28.3	68					
27	4.3	48%	28.3	68					
28	4.5	48%	28.3	68					
29	4.4	48%	28.3	68					
30	3.9	48%	28.3	68					
31	3.3	48%	28.3	68					
32	4.1	47%	28.3	68					
33	4.1	47%	28.3	68					
34	5.2	47%	28.3	69					
35	5.8	47%	28.3	69					
36	5.1	47%	28.3	68					
37	6.3	47%	28.3	68					
38	5.7	48%	28.3	68					
39	6.7	48%	28.5	68					
40	6.5	48%	28.3	68					
41	5.8	48%	28.5	68					
42	7.5	48%	28.3	68					
43	5.9	48%	28.3	68					
44	6.8	48%	28.3	68					
45	5.9	48%	28.5	68					
46	5.5	48%	28.5	68					
47	4.6	49%	28.5	69					
48	4.4	48%	28.5	70					

(x) Stripped (*) Low Battery (/) Tilting Occured